North America Emission Control Area Fuel Oil Non-Availability Report

Date of Issue 16-Dec-14

Field No	Field Name	
1	Report Form ID	ECA0100
2	Ship Operator Name	MUR SHIPPING BV
3	Vessel Name	African Wagtail
4	Flag Country	Bahamas
5	IMO ID Number	9649043
6	Date of ECA First Notice	7-Nov-14
7	Location of ECA First Notice	Kinuura
8	Name of Ports after First Notice	Vladivostok
9	Name of Last Port before ECA Entry	Panama Canal
10	Name of Port with Fuel Oil Supply Disruption	Vladivostok
11	Name of Original Fuel Supplier with Disruption	Nakhodka-Portbunker Co, Ltd.
12	Number of Fuel Suppliers Contacted	1 - Nakhodka-Portbunker Co, Ltd.
13	Date of Entry in the ECA	23-Dec-14
14	Time of Entry in the ECA	1:00
15	Sulfur Content of Non-Compliant Fuel Oil	0.98-1.06%
16	Projected Hours on Main Propulsion	About 12 hours
17	Name of First ECA POC	Brownsville
18	Compliance Fuel Oil Available at First POC?	No
19	Plan to Bunker Compliant Fuel Oil at First POC?	No - not available / waiting for re-test / no tank space for LSFO
20	Number of fuel suppliers contacted at First POC	3 - Bomin Bunker Oil / Martin Resource / OMS - O'rourke Marine Svcs
21	Name of Second POC	New Orleans
22	Compliant Fuel Oil at Second POC?	No
23	Plan to Bunker Compliance Fuel Oil at Second POC?	No - not available / waiting for re-test
24	Number of Fuel Suppliers Contacted at the Second POC?	3 - Chevron / Bomin Bunker Oil / Stone
25	Date of Exit from ECA?	On / About 05/01/2015
26	Time of Exit from ECA?	unknown
27	Has this vessel operated in the ECA in previous 12 months?	YES
28	Number of Separate Visits to the ECA	Three
29	Number of Ports visited in the ECA	Philadelphia, Norfolk and New Orleans
	·	Yes
31	Number of Submitted Reports	44
32	Designated Corporate Official Name	Mr. Arzan D Balsara
	Designated Corporate Official E-mail	ops.ae@murship.com
34	Designated Corporate Official Phone Number	97143415701
35	Description of Actions to Achieve Compliance	Upon departure Kinuura, we sailed to Vladivostok to load cargo and supply LSIFO (compliant fuel Oil). The bunker delivery note & supplier test certificate reflect sulphur content 0.98 % i.e. compliant fuel. However the vessel head owners did test on their own and their finding that the sulphur content 1.06 %. We are presently unsure whether the bunker delivery note and supplier test certificate are correct, or whether the survey undertaken by the vessel's head owners is correct. We are arranging a re-test which may well show that the fuel is in accordance with the supplier's information and is therefore compliant, but in view of the uncertainty we are filing this FONAR as a precautionary measure because we had planned to take on board LSIFO and believed that we had done so, we do not have tank space to bunker further LSIFO. Attached copy of the bunker delivery note and owners test certificate.